



## SHELDON CONSTRUCTION

FLOYD and JAMES SHELDON

Cellar Holes Dug - Back Fill - Grading - Etc.

— Fully Insured —

PAWLET, VERMONT 05761

Telephone 802-325-3404

December 30, 1992

Mark Coleman  
103 South Main Street  
Waterbury, VT 05671-0404

We took the advice of Mark Coleman and checked the river bank for signs of fuel contamination and found none.

We cleaned the hole #1 out where the tank had been removed. This is gravel down to a depth of app. 12' over clay. Just before we hit the clay there was a faint smell of diesel fuel. The water table is app. 1' above the clay. We put a well screen in to a depth of app. 14' and capped it as Mark advises. The soil that had a faint smell of diesel fuel was tested by Mark to have a reading of 10ppm.

We put the two <sup>243</sup>~~244~~ other test wells in and they were both the same. It was about 2' of gravel over clay. (This clay runs very deep, a neighbor drilled a well and went through 90' of clay.) These holes the water table is app. 1' from the surface. They were both clean and showed no signs of contamination. Monitoring wells were installed with a screen depth of app. 10'. the wells are in but we have no means or resources to monitoring them.

Sincerely,

Floyd R. Sheldon  
Sheldon Construction